

Client: Crown Property Management Inc.




Version	Created: 03/18/2024
V1	Measured: 03/15/2024

180 Dundas Street West  
Toronto, Ontario, Canada

**Suite 2103**

Please refer to corresponding  
BOMA Office 2017 Method A Area  
Chart:

180dundas-b17a-11a.pdf



This work product has been prepared by Extreme Measures Inc. pursuant to a contract with the Client for the sole benefit of and use by the Client. No third party may rely on this work product without the receipt of a reliance letter from Extreme Measures Inc.




This work product or portions thereof relies upon information provided by the Client and/or from third parties introduced by the Client that has not been independently verified by Extreme Measures Inc. Extreme Measures Inc. is not liable for any errors, omissions or inaccuracies that may result from such information.



Version	Created: 03/18/2024
<b>FP2A</b>	Measured: 03/15/2024

180 Dundas Street West  
Toronto, Ontario, Canada

Floor 21



This work product has been prepared by Extreme Measures Inc. pursuant to a contract with the Client for the sole benefit of and use by the Client. No third party may rely on this work product without the receipt of a reliance letter from Extreme Measures Inc.

This work product or portions thereof relies upon information provided by the Client and/or from third parties introduced by the Client that has not been independently verified by Extreme Measures Inc. Extreme Measures Inc. is not liable for any errors, omissions or inaccuracies that may result from such information.